

# COMPLETE BATHROOM REHAB DECEMBER 2017

**Willco Services LLC.**

**Sub-Contractors**

Sir's Carpentry Solutions LLC.

Watt1 Electrical Systems LLC.

RMD Price Plumbing LLC.

# Tile Missing-Molded Drywall



# Improperly Installed Tub Faucet



# Tile Missing-Molded Drywall





# Molded Ceiling Drywall



# Molded Ceiling Drywall



# Flooring Deteriorated



# Toilet Space Out Of Code





# Toilet Water Line Improperly Installed



# Toilet Waste Water Pipe Improperly Installed Through Heat Duct



# Molded Drywall Removed





# Toilet Waste Pipe Relocated





# Heat Duct Relocated From Floor



# New Sub-Floor



# New Sub-Floor





# New Sub-Floor





# New Ceiling Drywall



# New Drywall



# New Whirlpool Tub Installed



# Tub Water Lines Relocated





# Drywall Installation



# Drywall Installation



# Ceiling Drywall Finishing



# Drywall Finished and Primed





# Walls Primed



# Walls Painted



# New Flooring Installed



# Old Vanity





# Old Vanity Removed



# Vanity Water Lines Improperly Installed



# Vanity Water Lines Relocated





# Vanity Drywall Replaced Electrical Updated





# Vanity Drywall Replaced



# Vanity Walls Primed



# Vanity Walls Painted



# New Vanity Installed





# New Vanity Sink



# Vanity Lighting



# Vanity Lighted Makeup Mirror



# New Door Installed





# Cultured Marble Tub/Shower Walls Installed



# Cultured Marble Accessories Installed



# Tub Rain/Body Shower Faucet Installed



# New Toilet Installed





# Additional Space For Cabinet



# Digital Rain/Body Shower



# Finished Skylight



# Shower Door Installed





# Finished Tub/Shower

